

Japan	BUFFALO	WI-U2-433DHP	802.11a/b/g/n/ac 2.4/5GHz	N/A	N/A	N/A	N/A	N/A	N/A	N/A	OK	OK
Japan	BUFFALO	WI-U2-433DMS	802.11a/b/g/n/ac 2.4/5GHz	OK	OK	OK	OK	OK	OK	OK	OK	OK
Japan	TP-Link	Archer T4UH	802.11a/b/g/n/ac 2.4/5GHz	OK	OK	OK	OK	OK	OK	OK	OK	OK
Japan	BUFFALO	WI-U3-866DS	802.11a/b/g/n/ac 2.4/5GHz	OK	OK	OK	OK	OK	OK	OK	N/A	N/A
Germany	TP-Link	TL-WN823N (v1)	802.11b/g/n 2.4GHz	OK	OK	OK	OK	OK	OK	OK	N/A	N/A
Germany	TP-Link	TL-WN727N	802.11b/g/n 2.4GHz	OK	OK	OK	N/A	N/A	N/A	N/A	N/A	N/A
Germany	Digitus	DN-70542	802.11b/g/n 2.4GHz	OK	OK	OK	OK	OK	OK	OK	N/A	N/A
Germany	Sitecom	WLA-1001	802.11a/b/g/n 2.4/5GHz	OK	OK	OK	OK	OK	OK	OK	N/A	N/A
Germany	EnGenius	EUB1200AC	802.11a/b/g/n/ac 2.4/5GHz	OK	OK	OK	OK	OK	OK	OK	N/A	N/A
Germany	ASUS	USB-AC56	802.11a/b/g/n/ac 2.4/5GHz	OK	OK	OK	OK	OK	OK	OK	N/A	N/A
Germany	D-Link	DWA-172 (rev A1)	802.11a/b/g/n/ac 2.4/5GHz	OK	OK	OK	OK	OK	OK	OK	N/A	N/A
Germany	EDIMAX	EW-7811UTC	802.11a/b/g/n/ac 2.4/5GHz	OK	OK	OK	OK	OK	OK	OK	N/A	N/A
Germany	TP-Link	TL-WN821N (v4)	802.11b/g/n 2.4GHz	OK	OK	OK	OK	OK	OK	OK	N/A	N/A
Germany	D-Link	DWA-171 (rev A1)	802.11a/b/g/n/ac 2.4/5GHz	OK	OK	OK	OK	OK	OK	OK	N/A	N/A
Germany	NETGEAR	A6100	802.11a/b/g/n/ac 2.4/5GHz	OK	OK	OK	OK	OK	OK	OK	N/A	N/A
Germany	TP-Link	Archer T4U (v1)	802.11a/b/g/n/ac 2.4/5GHz	OK	OK	OK	OK	OK	OK	OK	N/A	N/A
Germany	Linksys	WUSB6300	802.11a/b/g/n/ac 2.4/5GHz	OK	OK	OK	OK	OK	OK	OK	N/A	N/A
Germany	D-Link	DWA-182	802.11a/b/g/n/ac 2.4/5GHz	OK	OK	OK	OK	OK	OK	OK	OK	OK
Germany	EDIMAX	EW-7811UAC	802.11a/b/g/n/ac 2.4/5GHz	OK	OK	OK	OK	OK	OK	OK	OK	OK
Germany	NETGEAR	A6100	802.11a/b/g/n/ac 2.4/5GHz	OK	OK	OK	OK	OK	OK	OK	OK	OK
Germany	EDIMAX	EW-7811DAC	802.11a/b/g/n/ac 2.4/5GHz	OK	OK	OK	OK	OK	OK	OK	OK	OK
Germany	EDIMAX	EW-7822UTC	802.11a/b/g/n/ac 2.4/5GHz	N/A	N/A	N/A	N/A	N/A	N/A	N/A	OK	OK
Germany	EDIMAX	EW-7822ULC	802.11a/b/g/n/ac 2.4/5GHz	N/A	N/A	N/A	N/A	N/A	N/A	N/A	OK	OK
Germany	EDIMAX	EW-7811Un V2	802.11b/g/n 2.4GHz	N/A	N/A	N/A	N/A	N/A	N/A	N/A	OK	OK
Germany	EDIMAX	EW-7833UAC	802.11a/b/g/n/ac 2.4/5GHz	N/A	N/A	N/A	N/A	N/A	N/A	N/A	OK	OK

JVCKENWOOD cannot guarantee the operation and will not take any responsibility whatsoever for this table.

It is likely to fail to operate with firmware update by manufacturer of the adaptor.

Customer can use the list at their own responsibility.